

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION II 245 PEACHTREE CENTER AVENUE N.E., SUITE 1200 ATLANTA, GEORGIA 30303-1200

November 10, 2022

Ms. Jamie Coleman Regulatory Affairs Director Southern Nuclear Operating Company 7825 River Road, BIN 63031 Waynesboro, GA 30830

SUBJECT: VOGTLE ELECTRIC GENERATING PLANT, UNITS 3 AND 4 - NRC

INTEGRATED INSPECTION REPORTS 05200025/2022005.

05200026/2022005

Dear Ms. Coleman:

On September 30, 2022, the U.S. Nuclear Regulatory Commission (NRC) completed an integrated inspection at the Vogtle Electric Generating Plant (VEGP), Units 3 and 4. On October 18, 2022, the NRC inspectors discussed the results of this inspection with Mr. G. Chick, VEGP Units 3 and 4 Executive Vice President, and other members of your staff.

The inspection examined a sample of construction activities conducted under your Combined License (COL) as it relates to safety and compliance with the Commission's rules and regulations and with the conditions of these documents. The inspectors reviewed selected procedures and records, observed activities, and interviewed personnel. This report also includes the final documentation for Unit 3 inspections, tests, analyses, and acceptance criteria (ITAAC) that were inspected prior to the issuance of the 10 CFR 52.103(g) finding on August 3, 2022, and previously documented in the 10 CFR 52.103(g) Basis Document for VEGP, Unit 3, located in the NRC's Agencywide Documents Access and Management System (ADAMS) at Accession No. ML20290A276.

Based on the results of this inspection, no findings of significance were identified. This letter, its enclosure, and your response (if any) will be made available for public inspection and copying at http://www.nrc.gov/reading-rm/adams.html and at the NRC Public Document Room in accordance with Title 10 of the Code of Federal Regulations 2.390, "Public Inspections, Exemptions, Requests for Withholding." Should you have any questions concerning this letter, please contact me at 404-997-4510.

J. Coleman 2

Sincerely,

Khouri, George signing on behalf of Coovert, Nicole on 11/10/22

Nicole Coovert, Chief Construction Inspection Branch 1 Division of Construction Oversight

Docket Nos.: 5200025, 5200026 License Nos: NPF-91, NPF-92

Enclosure(s):

NRC Inspection Report (IR) 05200025/2022005,

05200026/2022005 w/attachment: Supplemental Information

cc w/ encl: Distribution via LISTSERV

SUBJECT: VOGTLE ELECTRIC GENERATING PLANT, UNITS 3 AND 4 – NRC

INTEGRATED INSPECTION REPORTS 05200025/2022005,

05200026/2022005 Dated November 10, 2022

DISTRIBUTION:

M. Kowal, RII N. Doiley, RII M. Toth, RII S. Price, RII PUBLIC

ADAMS ACCESSION NUMBER: ML22314A070

X SUNSI Review		X Non-Sensitive Sensitive		X Publicly Available Non-Publicly Available	
OFFICE	RII/DCO	RII/DCO	RII/DCO	RII/DCO	
NAME	J. Vasquez	R. Mathis	B. Kemker	G.Khouri	
DATE	11/10/22	11/10/22	11/10/22	11/10/22	

OFFICIAL RECORD COPY

U.S. NUCLEAR REGULATORY COMMISSION Region II

Docket Numbers: 5200025

5200026

License Numbers: NPF-91

NPF-92

Report Numbers: 05200025/2022005

05200026/2022005

Licensee: Southern Nuclear Operating Company, Inc.

Facility: Vogtle Unit 3 and Unit 4

Location: Waynesboro, Ga

Inspection Dates: July 1, 2022 through September 30, 2022

Inspectors: G. Crespo, Senior Construction Inspector, Division of

Construction Oversight (DCO)

Y. Diaz-Castillo, Reactor Operations Engineer, Office of Nuclear Reactor Regulation (NRR), Quality Assurance

Vendor Inspection Branch

D. Dodson, Senior Reactor Inspector, Division of Reactor

Safety, Region IV

T. Fredette, Reactor Operations Engineer, NRR, Vogtle

Project Office

B. Griman, Resident Inspector, DCO

A. Johnson, Senior Construction Project Manager, DCO M. Keefe-Forsyth, Safety Culture Project Manager, NRR,

Reactor Assessment Branch

B. Kemker, Senior Resident Inspector, DCO J. Lizardi-Barreto, Construction Inspector, DCO R. Mathis, Senior Construction Inspector, DCO R. Patel, Senior Construction Inspector, DCO D. Terry-Ward, Construction Inspector, DCO J. Vasquez, Construction Inspector, DCO

D. Willis, Team Leader, NRR, Office of Enforcement

Approved by: Nicole Coovert, Chief

Construction Inspection Branch 1 Division of Construction Oversight

SUMMARY OF FINDINGS

Inspection Report (IR) 05200025/2022005, 05200026/2022005; 07/01/2022 through 09/30/2022; Vogtle Unit 3 and Unit 4 Combined License, integrated inspection report.

This report covers a three-month period of inspection by headquarters, regional, and resident inspectors. The NRC's program for overseeing the safe construction of commercial nuclear power reactors is described in IMC 2506, "Construction Reactor Oversight Process General Guidance and Basis Document."

Α.	NRC-Identified	and Self	Revealed	Findings
----	----------------	----------	----------	----------

None

B. Licensee-Identified Violations

None

REPORT DETAILS

Summary of Plant Construction Status

<u>Unit 3</u>: The licensee completed plant construction and testing necessary to satisfy all inspections, tests, analyses, and acceptance criteria (ITAAC) in Appendix C of the Unit 3 combined license (COL). The licensee made this notification to the NRC in a letter dated July 29, 2022 (ADAMS Accession No. ML22210A090). The NRC documented completion of its review of all ITAAC notifications and all ITAAC-related inspections in a letter dated August 3, 2022 (ADAMS Package Accession No. ML20290A280). The licensee worked to complete remaining construction activities and all required maintenance and surveillance tests to enter Mode 6 and load fuel in the reactor.

<u>Unit 4</u>: The licensee completed integrated flush and open vessel testing activities and was making preparations for closed vessel testing. The licensee continued installation of plant electrical cabinets, raceways, conduits, and cables.

1. CONSTRUCTION REACTOR SAFETY

Cornerstones: Design/Engineering, Procurement/Fabrication, Construction/Installation, Inspection/Testing

IMC 2503, Inspections, Tests, Analyses, and Acceptance Criteria (ITAAC) - Related Work Inspections

1A01 (Unit 3) ITAAC Number 3.3.00.07aa (789) / Family 09A

a. Inspection Scope

The inspectors performed a direct inspection of construction activities associated with ITAAC Number 3.3.00.07aa (789). The inspectors used the following NRC inspection procedures (IPs)/sections to perform this inspection:

- 65001.09-02.01 Physical Separation of Cables
- 65001.09-02.02 Attributes of Electrical Cable installation
- 65001.09-02.03 Documentation
- 65001.09-02.04 Problem Identification and Resolution
- 65001.A.02.02 Installation Records Review

The inspectors inspected raceways inside the containment building. The rooms inspected were the steam generator operating deck (room 11501), upper pressurizer compartment (room 11503), and lower automatic depressurization system (ADS) valve area (room 11603). The inspectors conducted walkdowns of the raceways inside the rooms to verify separation between raceways that route Class 1E cables of different divisions, and between raceways that route Class 1E cables and raceways that route non-Class 1E cables. During the walkdown, the inspectors verified that the raceways and cables were identified by the appropriate color code and the division cables were routed in their respective raceways. The inspectors also walked down cables installed in trays to verify that cable fill design requirements were met, as applicable.

The inspectors reviewed applicable construction specifications, installation procedures, written instructions, drawings, work packages, and quality control inspection reports to verify raceways that route Class 1E cables were installed in accordance with design requirements. The inspectors reviewed work packages, test and inspection records, and cable pull tickets to confirm the non-Class 1E cables needed to meet the ITAAC requirements of Appendix C of the COL were installed at the time of ITAAC verification.

For the raceways installed in these rooms, the inspectors verified the size, material, and style were as specified in design documents and work procedures. The inspectors verified raceway supports were located at points specified in approved instructions and that maximum distance between supports were not exceeded. Inspectors also verified fittings and clamps were installed according to work procedures. Additionally, the inspectors reviewed the licensee's corrective actions for issues entered into the corrective action program (CAP) to verify issues were identified, evaluated, and corrected.

The inspectors reviewed ITAAC Technical Report SV3-1100-ITR-CTMTIR, Revision 0, SV3-1100-ITR-CTMT, Revision 0 and supporting documentation to determine if the licensee's inspection results inside containment confirmed the following:

- Class 1E electrical cables, and communication cables associated with only one division, and the raceways that route these cables inside containment are identified by the appropriate color code.
- Class 1E electrical cables and communication cables associated with only one division were routed in raceways assigned to the same division and there were no other safety division electrical cables in a raceway assigned to a different division.
- Separation between raceways that route Class 1E cables of different divisions, and between raceways that route Class 1E cables and raceways that route non-Class 1E cables met separation requirements inside containment.
- Where minimum separation distances were not met inside containment, circuits were run in enclosed raceways or barriers.

b. Findings

No findings were identified.

1A02 (Unit 3) ITAAC Number 3.3.00.07ab (790) / Family 09A

a. Inspection Scope

The inspectors performed a direct inspection of construction activities associated with ITAAC Number 3.3.00.07ab (790). The inspectors used the following NRC IPs/sections to perform this inspection:

- 65001.09-02.01 Physical Separation of Cables
- 65001.09-02.02 Attributes of Electrical Cable installation
- 65001.09-02.03 Documentation
- 65001.09-02.04 Problem Identification and Resolution
- 65001.A.02.02 Installation Records Review

The inspectors inspected raceways inside the non-radiologically controlled area of the auxiliary building. The rooms inspected included the following:

- 12305 Division D I&C Penetration Room (Fire Area 1201 AF 03)
- 12105 Division D Battery Room (Fire Area 1201 AF 03)
- 12104 Division B Battery Room 1 (Fire Area 1201 AF 02)
- 12203 Division C DC Equipment Room (Fire Area 1202 AF 03)
- 12207 Division B DC Equipment Room (Fire Area 1202 AF 02)

The inspectors conducted walkdowns of the raceways inside the rooms to verify separation between raceways that route Class 1E cables of different divisions, and between raceways that route Class 1E cables and raceways that route non-Class 1E cables. During the walkdown, the inspectors verified that the raceways and cables were identified by the appropriate color code and the division cables were routed in their respective raceways. The inspectors also walked down cables installed in trays to verify that cable fill design requirements were met, as applicable.

The inspectors reviewed applicable construction specifications, installation procedures, written instructions, drawings, work packages, and quality control inspection reports to verify raceways that route Class 1E cables were installed in accordance with design requirements. The inspectors reviewed work packages, test and inspection records, and cable pull tickets to confirm the non-Class 1E cables needed to meet the ITAAC requirements of Appendix C of the COL were installed at the time of ITAAC verification.

For the raceways installed in these rooms, the inspectors verified the size, material, and style were as specified in design documents and work procedures. The inspectors verified raceway supports were located at points specified in approved instructions and that maximum distance between supports were not exceeded. Inspectors also verified fittings and clamps were installed according to work procedures. Additionally, the inspectors reviewed the licensee's corrective actions for issues entered into the CAP to verify issues were identified, evaluated, and corrected.

The inspectors reviewed ITAAC Technical Report SV3-1200-ITR-AUXNRDIR, Revision 0, SV3-1200-ITR-AUXNRD, Revision 0 and supporting documentation to determine if the licensee's inspection results inside the non-radiologically controlled area of the auxiliary building confirmed the following:

- Class 1E electrical cables, and communication cables associated with only one division, and the raceways that route these cables in the non-radiologically controlled area of the auxiliary building were identified by the appropriate color code.
- Class 1E electrical cables and communication cables in the non-radiologically controlled area of the auxiliary building associated with only one division were routed in raceways assigned to the same division. There are no other safety division electrical cables in a raceway assigned to a different division.
- Separation between Class 1E divisions in the non-radiologically controlled area of the auxiliary building was consistent with Appendix C of the COL, Table 3.3-3.
- Separation between raceways that route Class 1E cables of different divisions, and between raceways that route Class 1E cables and raceways that route non-Class 1E cables met separation requirements inside the non-radiologically controlled area of the auxiliary building (limited hazard areas).
- Where minimum separation distances were not met inside the non-radiologically controlled area of the auxiliary building, circuits were run in enclosed raceways or barriers.

b. Findings

No findings were identified.

1A03 (Unit 3) ITAAC Number 3.3.00.07ba (792) / Family 09A

a. Inspection Scope

The inspectors performed a direct inspection of construction activities associated with ITAAC Number 3.3.00.07ba (792). The inspectors used the following NRC IPs/sections to perform this inspection:

- 65001.09-02.01 Physical Separation of Cables
- 65001.09-02.02 Attributes of Electrical Cable installation
- 65001.09-02.03 Documentation
- 65001.09-02.04 Problem Identification and Resolution
- 65001.A.02.02 Installation Records Review

The inspectors inspected raceways inside the containment building. The rooms inspected were the steam generator operating deck (room 11501), upper pressurizer compartment (room 11503), and lower ADS valve area (room 11603). The inspectors conducted walkdowns of the raceways inside the rooms to verify separation between raceways that route Class 1E cables of different divisions, and between raceways that route Class 1E cables and raceways that route non-Class 1E cables. During the walkdown, the inspectors verified that the raceways and cables were identified by the appropriate color code and the division cables were routed in their respective raceways.

The inspectors also walked down cables installed in trays to verify that cable fill design requirements were met, as applicable.

The inspectors reviewed applicable construction specifications, installation procedures, written instructions, drawings, work packages, and quality control inspection reports to verify raceways that route Class 1E cables were installed in accordance with design requirements. The inspectors reviewed work packages, test and inspection records, and cable pull tickets to confirm the non-Class 1E cables needed to meet the ITAAC requirements of Appendix C of the COL were installed at the time of ITAAC verification.

For the raceways installed in these rooms, the inspectors verified the size, material, and style were as specified in design documents and work procedures. The inspectors verified raceway supports were located at points specified in approved instructions and that maximum distance between supports were not exceeded. Inspectors also verified fittings and clamps were installed according to work procedures. Additionally, the inspectors reviewed the licensee's corrective actions for issues entered into the CAP to verify issues were identified, evaluated, and corrected.

The inspectors reviewed ITAAC Technical Report SV3-1100-ITR-CTMTIR, Revision 0, SV3-1100-ITR-CTMT, Revision 0 and supporting documentation to determine if the licensee's inspection results inside containment confirmed the following:

- Class 1E electrical cables, and communication cables associated with only one division, and the raceways that route these cables inside containment are identified by the appropriate color code.
- Class 1E electrical cables and communication cables associated with only one division were routed in raceways assigned to the same division and there were no other safety division electrical cables in a raceway assigned to a different division.
- Separation between raceways that route Class 1E cables of different divisions, and between raceways that route Class 1E cables and raceways that route non-Class 1E cables met separation requirements inside containment.
- Where minimum separation distances were not met inside containment, circuits were run in enclosed raceways or barriers.

b. Findings

No findings were identified.

1A04 (Unit 3) ITAAC Number 3.3.00.07bb (793) / Family 09A

a. Inspection Scope

The inspectors performed a direct inspection of construction activities associated with ITAAC Number 3.3.00.07bb (793). The inspectors used the following NRC IPs/sections to perform this inspection:

- 65001.09-02.01 Physical Separation of Cables
- 65001.09-02.02 Attributes of Electrical Cable installation
- 65001.09-02.03 Documentation

- 65001.09-02.04 Problem Identification and Resolution
- 65001.A.02.02 Installation Records Review

The inspectors inspected raceways inside the non-radiologically controlled area of the auxiliary building. The rooms inspected included the following:

- 12305 Division D I&C Penetration Room (Fire Area 1201 AF 03)
- 12105 Division D Battery Room (Fire Area 1201 AF 03)
- 12104 Division B Battery Room 1 (Fire Area 1201 AF 02)
- 12203 Division C DC Equipment Room (Fire Area 1202 AF 03)
- 12207 Division B DC Equipment Room (Fire Area 1202 AF 02)

The inspectors conducted walkdowns of the raceways inside the rooms to verify separation between raceways that route Class 1E cables of different divisions, and between raceways that route Class 1E cables and raceways that route non-Class 1E cables. During the walkdown, the inspectors verified that the raceways and cables were identified by the appropriate color code and the division cables were routed in their respective raceways. The inspectors also walked down cables installed in trays to verify that cable fill design requirements were met, as applicable.

The inspectors reviewed applicable construction specifications, installation procedures, written instructions, drawings, work packages, and quality control inspection reports to verify raceways that route Class 1E cables were installed in accordance with design requirements. The inspectors reviewed work packages, test and inspection records, and cable pull tickets to confirm the non-Class 1E cables needed to meet the ITAAC requirements of Appendix C of the COL were installed at the time of ITAAC verification.

For the raceways installed in these rooms, the inspectors verified the size, material, and style were as specified in design documents and work procedures. The inspectors verified raceway supports were located at points specified in approved instructions and that maximum distance between supports were not exceeded. Inspectors also verified fittings and clamps were installed according to work procedures. Additionally, the inspectors reviewed the licensee's corrective actions for issues entered into the CAP to verify issues were identified, evaluated, and corrected.

The inspectors reviewed ITAAC Technical Report SV3-1200-ITR-AUXNRDIR, Revision 0, SV3-1200-ITR-AUXNRD, Revision 0 and supporting documentation to determine if the licensee's inspection results inside the non-radiologically controlled area of the auxiliary building confirmed the following:

- Class 1E electrical cables, and communication cables associated with only one division, and the raceways that route these cables in the non-radiologically controlled area of the auxiliary building were identified by the appropriate color code.
- Class 1E electrical cables and communication cables in the non-radiologically controlled area of the auxiliary building associated with only one division were routed in raceways assigned to the same division. There are no other safety division electrical cables in a raceway assigned to a different division.

- Separation between Class 1E divisions in the non-radiologically controlled area of the auxiliary building was consistent with Appendix C of the COL, Table 3.3-3.
- Separation between raceways that route Class 1E cables of different divisions, and between raceways that route Class 1E cables and raceways that route non-Class 1E cables met separation requirements inside the non-radiologically controlled area of the auxiliary building (limited hazard areas).
- Where minimum separation distances were not met inside the non-radiologically controlled area of the auxiliary building, circuits were run in enclosed raceways or barriers.

b. Findings

No findings were identified.

1A05 (Unit 3) ITAAC Number 3.3.00.07c.i.a (795) / Family 09A

a. Inspection Scope

The inspectors performed a direct inspection of construction activities associated with ITAAC Number 3.3.00.07c.i.a (795). The inspectors used the following NRC IPs/sections to perform this inspection:

- 65001.09-02.01 Physical Separation of Cables
- 65001.09-02.02 Attributes of Electrical Cable installation
- 65001.09-02.03 Documentation
- 65001.09-02.04 Problem Identification and Resolution
- 65001.A.02.02 Installation Records Review

The inspectors inspected raceways inside the non-radiologically controlled area of the auxiliary building. The rooms inspected included the following:

- 12305 Division D I&C Penetration Room (Fire Area 1201 AF 03)
- 12105 Division D Battery Room (Fire Area 1201 AF 03)
- 12104 Division B Battery Room 1 (Fire Area 1201 AF 02)
- 12203 Division C DC Equipment Room (Fire Area 1202 AF 03)
- 12207 Division B DC Equipment Room (Fire Area 1202 AF 02)

The inspectors conducted walkdowns of the raceways inside the rooms to verify separation between raceways that route Class 1E cables of different divisions, and between raceways that route Class 1E cables and raceways that route non-Class 1E cables. During the walkdown, the inspectors verified that the raceways and cables were identified by the appropriate color code and the division cables were routed in their respective raceways. The inspectors also walked down cables installed in trays to verify that cable fill design requirements were met, as applicable.

The inspectors reviewed applicable construction specifications, installation procedures, written instructions, drawings, work packages, and quality control inspection reports to verify raceways that route Class 1E cables were installed in accordance with design requirements. The inspectors reviewed work packages, test and inspection records, and cable pull tickets to confirm the non-Class 1E cables needed to meet the ITAAC requirements of Appendix C of the COL were installed at the time of ITAAC verification.

For the raceways installed in these rooms, the inspectors verified the size, material, and style were as specified in design documents and work procedures. The inspectors verified raceway supports were located at points specified in approved instructions and that maximum distance between supports were not exceeded. Inspectors also verified fittings and clamps were installed according to work procedures. Additionally, the inspectors reviewed the licensee's corrective actions for issues entered into the CAP to verify issues were identified, evaluated, and corrected.

The inspectors reviewed ITAAC Technical Report SV3-1200-ITR-AUXNRDIR, Revision 0, SV3-1200-ITR-AUXNRD, Revision 0 and supporting documentation to determine if the licensee's inspection results inside the non-radiologically controlled area of the auxiliary building confirmed the following:

- Class 1E electrical cables, and communication cables associated with only one division, and the raceways that route these cables in the non-radiologically controlled area of the auxiliary building were identified by the appropriate color code.
- Class 1E electrical cables and communication cables in the non-radiologically controlled area of the auxiliary building associated with only one division were routed in raceways assigned to the same division. There are no other safety division electrical cables in a raceway assigned to a different division.
- Separation between Class 1E divisions in the non-radiologically controlled area of the auxiliary building was consistent with Appendix C of the COL, Table 3.3-3.
- Separation between raceways that route Class 1E cables of different divisions, and between raceways that route Class 1E cables and raceways that route non-Class 1E cables met separation requirements inside the non-radiologically controlled area of the auxiliary building (limited hazard areas).
- Where minimum separation distances were not met inside the non-radiologically controlled area of the auxiliary building, circuits were run in enclosed raceways or barriers.

b. Findings

No findings were identified.

1A06 (Unit 3) ITAAC Number 3.3.00.07d.ii.a (800) / Family 09A

a. Inspection Scope

The inspectors performed a direct inspection of construction activities associated with ITAAC Number 3.3.00.07d.ii.a (800). The inspectors used the following NRC IPs/sections to perform this inspection:

- 65001.09-02.01 Physical Separation of Cables
- 65001.09-02.02 Attributes of Electrical Cable installation
- 65001.09-02.03 Documentation
- 65001.09-02.04 Problem Identification and Resolution
- 65001.A.02.02 Installation Records Review

The inspectors inspected raceways inside the containment building. The rooms inspected were the steam generator operating deck (room 11501), upper pressurizer compartment (room 11503), and lower ADS valve area (room 11603). The inspectors conducted walkdowns of the raceways inside the rooms to verify separation between raceways that route Class 1E cables of different divisions, and between raceways that route Class 1E cables and raceways that route non-Class 1E cables. During the walkdown, the inspectors verified that the raceways and cables were identified by the appropriate color code and the division cables were routed in their respective raceways.

The inspectors also walked down cables installed in trays to verify that cable fill design requirements were met, as applicable.

The inspectors reviewed applicable construction specifications, installation procedures, written instructions, drawings, work packages, and quality control inspection reports to verify raceways that route Class 1E cables were installed in accordance with design requirements. The inspectors reviewed work packages, test and inspection records, and cable pull tickets to confirm the non-Class 1E cables needed to meet the ITAAC requirements of Appendix C of the COL were installed at the time of ITAAC verification.

For the raceways installed in these rooms, the inspectors verified the size, material, and style were as specified in design documents and work procedures. The inspectors verified raceway supports were located at points specified in approved instructions and that maximum distance between supports were not exceeded. Inspectors also verified fittings and clamps were installed according to work procedures. Additionally, the inspectors reviewed the licensee's corrective actions for issues entered into the CAP to verify issues were identified, evaluated, and corrected.

The inspectors reviewed ITAAC Technical Report SV3-1100-ITR-CTMTIR, Revision 0, SV3-1100-ITR-CTMT, Revision 0 and supporting documentation to determine if the licensee's inspection results inside containment confirmed the following:

- Class 1E electrical cables, and communication cables associated with only one division, and the raceways that route these cables inside containment are identified by the appropriate color code.
- Class 1E electrical cables and communication cables associated with only one division were routed in raceways assigned to the same division and there were no other safety division electrical cables in a raceway assigned to a different division.
- Separation between raceways that route Class 1E cables of different divisions, and between raceways that route Class 1E cables and raceways that route non-Class 1E cables met separation requirements inside containment.
- Where minimum separation distances were not met inside containment, circuits were run in enclosed raceways or barriers.

b. Findings

No findings were identified.

1A07 (Unit 3) ITAAC Number 3.3.00.07d.ii.b (801) / Family 09A

a. Inspection Scope

The inspectors performed a direct inspection of construction activities associated with ITAAC Number 3.3.00.07d.ii.b (801). The inspectors used the following NRC IPs/sections to perform this inspection:

- 65001.09-02.01 Physical Separation of Cables
- 65001.09-02.02 Attributes of Electrical Cable installation
- 65001.09-02.03 Documentation

- 65001.09-02.04 Problem Identification and Resolution
- 65001.A.02.02 Installation Records Review

The inspectors inspected raceways inside the non-radiologically controlled area of the auxiliary building. The rooms inspected included the following:

- 12305 Division D I&C Penetration Room (Fire Area 1201 AF 03)
- 12105 Division D Battery Room (Fire Area 1201 AF 03)
- 12104 Division B Battery Room 1 (Fire Area 1201 AF 02)
- 12203 Division C DC Equipment Room (Fire Area 1202 AF 03)
- 12207 Division B DC Equipment Room (Fire Area 1202 AF 02)

The inspectors conducted walkdowns of the raceways inside the rooms to verify separation between raceways that route Class 1E cables of different divisions, and between raceways that route Class 1E cables and raceways that route non-Class 1E cables. During the walkdown, the inspectors verified that the raceways and cables were identified by the appropriate color code and the division cables were routed in their respective raceways. The inspectors also walked down cables installed in trays to verify that cable fill design requirements were met, as applicable.

The inspectors reviewed applicable construction specifications, installation procedures, written instructions, drawings, work packages, and quality control inspection reports to verify raceways that route Class 1E cables were installed in accordance with design requirements. The inspectors reviewed work packages, test and inspection records, and cable pull tickets to confirm the non-Class 1E cables needed to meet the ITAAC requirements of Appendix C of the COL were installed at the time of ITAAC verification.

For the raceways installed in these rooms, the inspectors verified the size, material, and style were as specified in design documents and work procedures. The inspectors verified raceway supports were located at points specified in approved instructions and that maximum distance between supports were not exceeded. Inspectors also verified fittings and clamps were installed according to work procedures. Additionally, the inspectors reviewed the licensee's corrective actions for issues entered into the CAP to verify issues were identified, evaluated, and corrected.

The inspectors reviewed ITAAC Technical Report SV3-1200-ITR-AUXNRDIR, Revision 0, SV3-1200-ITR-AUXNRD, Revision 0 and supporting documentation to determine if the licensee's inspection results inside the non-radiologically controlled area of the auxiliary building confirmed the following:

- Class 1E electrical cables, and communication cables associated with only one division, and the raceways that route these cables in the non-radiologically controlled area of the auxiliary building were identified by the appropriate color code.
- Class 1E electrical cables and communication cables in the non-radiologically controlled area of the auxiliary building associated with only one division were routed in raceways assigned to the same division. There are no other safety division electrical cables in a raceway assigned to a different division.

- Separation between Class 1E divisions in the non-radiologically controlled area of the auxiliary building was consistent with Appendix C of the COL, Table 3.3-3.
- Separation between raceways that route Class 1E cables of different divisions, and between raceways that route Class 1E cables and raceways that route non-Class 1E cables met separation requirements inside the non-radiologically controlled area of the auxiliary building (limited hazard areas).
- Where minimum separation distances were not met inside the non-radiologically controlled area of the auxiliary building, circuits were run in enclosed raceways or barriers.

b. <u>Findings</u>

No findings were identified.

1A08 (Unit 3) ITAAC Number 3.3.00.07d.iii.a (803) / Family 09A

a. Inspection Scope

The inspectors performed a direct inspection of construction activities associated with ITAAC Number 3.3.00.07d.iii.a (803). The inspectors used the following NRC IPs/sections to perform this inspection:

- 65001.09-02.01 Physical Separation of Cables
- 65001.09-02.03 Documentation
- 65001.09-02.04 Problem Identification and Resolution
- 65001.A.02.02 Installation Records Review

The inspectors inspected raceways inside the containment building. The rooms inspected were the steam generator operating deck (room 11501), upper pressurizer compartment (room 11503), and lower ADS valve area (room 11603). The inspectors conducted walkdowns of the raceways inside the rooms to verify separation between raceways that route Class 1E cables of different divisions, and between raceways that route Class 1E cables and raceways that route non-Class 1E cables. During the walkdown, the inspectors verified that the raceways and cables were identified by the appropriate color code and the division cables were routed in their respective raceways. The inspectors also walked down cables installed in trays to verify that cable fill design requirements were met, as applicable.

The inspectors reviewed applicable construction specifications, installation procedures, written instructions, drawings, work packages, and quality control inspection reports to verify raceways that route Class 1E cables were installed in accordance with design requirements. The inspectors reviewed work packages, test and inspection records, and cable pull tickets to confirm the non-Class 1E cables needed to meet the ITAAC requirements of Appendix C of the COL were installed at the time of ITAAC verification.

For the raceways installed in these rooms, the inspectors verified the size, material, and style were as specified in design documents and work procedures. The inspectors verified raceway supports were located at points specified in approved instructions and that maximum distance between supports were not exceeded.

Inspectors also verified fittings and clamps were installed according to work procedures. Additionally, the inspectors reviewed the licensee's corrective actions for issues entered into the CAP to verify issues were identified, evaluated, and corrected.

The inspectors reviewed ITAAC Technical Report SV3-1100-ITR-CTMTIR, Revision 0, SV3-1100-ITR-CTMT, Revision 0 and supporting documentation to determine if the licensee's inspection results inside containment confirmed the following:

- Class 1E electrical cables, and communication cables associated with only one division, and the raceways that route these cables inside containment are identified by the appropriate color code.
- Class 1E electrical cables and communication cables associated with only one division were routed in raceways assigned to the same division and there were no other safety division electrical cables in a raceway assigned to a different division.
- Separation between raceways that route Class 1E cables of different divisions, and between raceways that route Class 1E cables and raceways that route non-Class 1E cables met separation requirements inside containment.
- Where minimum separation distances were not met inside containment, circuits were run in enclosed raceways or barriers.

b. Findings

No findings were identified.

1A09 (Unit 3) ITAAC Number 3.3.00.07d.iii.b (804) / Family 09A

a. Inspection Scope

The inspectors performed a direct inspection of construction activities associated with ITAAC Number 3.3.00.07d.iii.b (804). The inspectors used the following NRC IPs/sections to perform this inspection:

- 65001.09-02.01 Physical Separation of Cables
- 65001.09-02.02 Attributes of Electrical Cable installation
- 65001.09-02.03 Documentation
- 65001.09-02.04 Problem Identification and Resolution
- 65001.A.02.02 Installation Records Review

The inspectors inspected raceways inside the non-radiologically controlled area of the auxiliary building. The rooms inspected included the following:

- 12305 Division D I&C Penetration Room (Fire Area 1201 AF 03)
- 12105 Division D Battery Room (Fire Area 1201 AF 03)
- 12104 Division B Battery Room 1 (Fire Area 1201 AF 02)
- 12203 Division C DC Equipment Room (Fire Area 1202 AF 03)
- 12207 Division B DC Equipment Room (Fire Area 1202 AF 02)

The inspectors conducted walkdowns of the raceways inside the rooms to verify separation between raceways that route Class 1E cables of different divisions, and between raceways that route Class 1E cables and raceways that route non-Class 1E cables. During the walkdown, the inspectors verified that the raceways and cables were identified by the appropriate color code and the division cables were routed in their respective raceways. The inspectors also walked down cables installed in trays to verify that cable fill design requirements were met, as applicable.

The inspectors reviewed applicable construction specifications, installation procedures, written instructions, drawings, work packages, and quality control inspection reports to verify raceways that route Class 1E cables were installed in accordance with design requirements. The inspectors reviewed work packages, test and inspection records, and cable pull tickets to confirm the non-Class 1E cables needed to meet the ITAAC requirements of Appendix C of the COL were installed at the time of ITAAC verification.

For the raceways installed in these rooms, the inspectors verified the size, material, and style were as specified in design documents and work procedures. The inspectors verified raceway supports were located at points specified in approved instructions and that maximum distance between supports were not exceeded. Inspectors also verified fittings and clamps were installed according to work procedures. Additionally, the inspectors reviewed the licensee's corrective actions for issues entered into the CAP to verify issues were identified, evaluated, and corrected.

The inspectors reviewed ITAAC Technical Report SV3-1200-ITR-AUXNRDIR, Revision 0, SV3-1200-ITR-AUXNRD, Revision 0 and supporting documentation to determine if the licensee's inspection results inside the non-radiologically controlled area of the auxiliary building confirmed the following:

- Class 1E electrical cables, and communication cables associated with only one division, and the raceways that route these cables in the non-radiologically controlled area of the auxiliary building were identified by the appropriate color code.
- Class 1E electrical cables and communication cables in the non-radiologically controlled area of the auxiliary building associated with only one division were routed in raceways assigned to the same division. There are no other safety division electrical cables in a raceway assigned to a different division.
- Separation between Class 1E divisions in the non-radiologically controlled area of the auxiliary building was consistent with Appendix C of the COL, Table 3.3-3.
- Separation between raceways that route Class 1E cables of different divisions, and between raceways that route Class 1E cables and raceways that route non-Class 1E cables met separation requirements inside the non-radiologically controlled area of the auxiliary building (limited hazard areas).
- Where minimum separation distances were not met inside the non-radiologically controlled area of the auxiliary building, circuits were run in enclosed raceways or barriers.

b. Findings

No findings were identified.

1A10 (Unit 3) ITAAC Number 3.3.00.07d.iv.b (807) / Family 09A

a. Inspection Scope

The inspectors performed a direct inspection of construction activities associated with ITAAC Number 3.3.00.07d.iv.b (807). The inspectors used the following NRC IP/sections to perform this inspection:

65001.09-02.03 - Documentation

The inspectors reviewed ITAAC Technical Report SV3-CSR-ITR-800807, Unit 3 Cable Separation Report for Analysis: ITAAC 3.3.00.07d.iv.b, Revision 2, to verify areas inside the non-radiological controlled area of the auxiliary building were analyzed, as specified in Table 3.3-6 of Appendix C of the Vogtle Unit 3 COL, for separation distances less than those required by ITAAC and not provided with enclosed raceways or barriers.

The inspectors reviewed engineering and design coordination report (E&DCR) APP-G1-GEF-850217, revision 0. This E&DCR documents the analysis requested by engineering services request (ESR) number 50144956. The ESR identified that the installation of the leaky coax cables used as part of the land mobil radio system distributed antenna system were not in compliance with the Institute of Electrical and Electronic Engineers (IEEE) 384 separation distances listed in APP-G1-V8-001 Appendix B and Appendix H. Analysis, as specified in Table 3.3-6 of Appendix C of the Vogtle Unit 3 COL for this ITAAC was required to evaluate this condition.

b. Findings

No findings were identified.

1A11 (Unit 4) ITAAC Number 2.2.01.11a.i (114) / Family 07E

a. Inspection Scope

The inspectors performed a direct inspection of construction activities associated with ITAAC Number 2.2.01.11a.i (114). The inspectors used the following NRC IPs/sections to perform this inspection:

- 65001.07-02.01 General Installation
- 65001.E-02.04-Documentation
- 65001.E-02.06-Problem Identification and Resolution

The inspectors reviewed the equipment qualification reconciliation reports (EQRR) for spent fuel pool cooling system (SFS) and component cooling water system (CCS) containment isolation motor-operated valves (MOV) SFS-PL-V034 and CCS-PL-V207, respectively, to determine whether the licensee assessed work packages, design changes, and nonconformances to confirm the as-built configuration, including anchorage, were seismically bounded by the tests or type tests, as required by

Appendix C of the Unit 4 COL, and in accordance with data sheets SV4-PV11-Z0D-123 and SV4-PV11-Z0D-124 and design specification SV4-PV11-Z0-001.

The inspectors reviewed the licensee's methodology and selection of applicable work orders, data sheets, and design drawings, to determine whether the inspections and analyses demonstrated the as-built installed MOVs were bounded by tests or type tests. The inspectors reviewed the equipment qualification summary reports and equipment qualification data packages to determine whether installation restrictions were translated to the drawings and EQRRs.

The inspectors conducted a field walkdown to inspect the as-built installation of the MOVs. The inspectors verified each valve's make/model/serial number, mounting orientation, and location. The inspectors also verified the mechanical and electrical connections were bounded by the tested conditions.

The inspectors interviewed licensing personnel to determine how inspection and analysis were performed for applicable nonconformances and E&DCRs issued during fabrication, handling, installation, and testing to verify deviations were bounded by the seismically analyzed conditions.

b. Findings

No findings were identified.

1A12 (Unit 4) ITAAC Number 2.2.03.08c.iii (182) / Family 03A

a. Inspection Scope

The inspectors performed a direct inspection of construction activities associated with ITAAC Number 2.2.03.08c.iii (182). The inspectors used the following NRC IP/section to perform this inspection:

65001.A- As-Built Attributes for SSCs associated with ITAAC

The inspectors performed an inspection to verify both Unit 4 core makeup tank (CMT) inlet lines from the reactor coolant system (RCS) cold legs had no downward sloping sections between the connections to the RCS and the high point of the lines as specified in Table 2.2.3-4 of Appendix C of the Vogtle Unit 4 COL. Similarly, the inspectors performed an inspection to verify the Unit 4 passive residual heat removal heat exchanger line from the RCS hot leg had no downward sloping sections between the connection to the RCS and the high point of the line as specified in Table 2.2.3-4 of Appendix C of the Vogtle Unit 4 COL. This inspection involved three piping sections consisting of seven pipe segments (i.e., three segments from the passive residual heat removal heat exchanger to RCS hot leg and two segments each for CMT A and CMT B from the RCS cold legs). The inspectors performed a walkdown of the three piping sections with the licensee, observed the licensee measure the slope of the two CMT lines, and performed independent measurements to verify the as-built piping was consistent with the as-built drawings. In addition, the inspectors reviewed quality records including the principal closure document (PCD), survey results, and as-built elevation drawings to verify the lines had no downward sloping sections between the connection to the RCS and the high point of the lines to satisfy the ITAAC.

b. Findings

No findings were identified.

1A13 (Unit 4) ITAAC Number 2.2.03.08c.vi.03 (191) / Family 06A

a. Inspection Scope

The inspectors performed a direct inspection of construction activities associated with ITAAC Number 2.2.03.08c.vi.03 (191). The inspectors used the following NRC IPs/sections to perform this inspection:

- 65001.A- As-Built Attributes for SSCs associated with ITAAC
- 65001.A.02.03 Independent Assessment/Measurement Inspection

The inspectors performed an inspection to verify the Unit 4 in-containment refueling water storage tank (IRWST) calculated volume was greater than, or equal, to 73,100 cubic feet between the tank outlet connection and the tank overflow as specified in Table 2.2.3-4 of Appendix C of the Vogtle Unit 4 COL. The inspectors reviewed approved drawings for the IRWST and its internal structures and components, reviewed the design calculation for the IRWST's volume, compared the survey results with dimensions from the drawings and the design calculation, and reviewed the licensees' determination of the IRWST's volume based on the survey results.

b. Findings

No findings were identified.

1A14 (Unit 4) ITAAC Number 2.5.01.04 (519) / Family 10F

a. <u>Inspection Scope</u>

The inspectors performed a direct inspection of construction activities associated with ITAAC Number 2.5.01.04 (519). The inspectors used the following NRC IP/sections to perform this inspection:

• 65001.10.02.02 – Inspection Activities

The inspectors conducted a review of SV4-DAS-ITR-800519 and APP-GW-GLR-623 to verify the design process used to develop the diverse actuation system (DAS) hardware and software during the installation phase defined the organizational responsibilities, activities, and configuration management controls for the performance of tests and inspections. Specifically, the inspectors reviewed the electrical equipment installation work package, SV4-DAS-JDW-1107744, to verify DAS and squib valve control cabinets were installed and inspected in accordance with applicable installation procedures including 26139-000-4MP-T81C-N3301.

The inspectors reviewed testing procedure B-GEN-ITPCI-002 to verify specific instructions and requirements were included for prerequisite and initial conditions, initial equipment setup, initial energization, power supply checks, current leakage checks. equipment restoration, and acceptance criteria. Westinghouse field chance notice SV4-GW-GCW-0126 was reviewed to verify the software installation process provided instructions and requirements for site specific equipment identification, supporting documentation and references, required steps and inspections to be performed to upgrade the Operating System, installing the replacement Antivirus product, installing the updated Application Software, configuring the software, and post installation verifications.

b. Findings

No findings were identified.

1A15 (Unit 4) ITAAC Number 3.3.00.07e (812) / Family 09A

a. Inspection Scope

The inspectors performed a direct inspection of construction activities associated with ITAAC Number 3.3.00.07e (812). The inspectors used the following NRC IPs/sections to perform this inspection:

- 65001.09-02.01 Physical Separation of Cables
- 65001.09-02.03 Documentation

The inspectors reviewed the routing and separation of the Class 1E communication cables for the protection and safety monitoring system (PMS) to verify the as-built configuration met the acceptance criteria specified in the Updated Final Safety Analysis Report Section 8.3.2.4 and in accordance with the acceptance criteria of ITAAC 3.3.00.07e of Appendix C to the Vogtle Unit 4 COL.

Specifically, the inspectors reviewed cable pull tickets to determine routing methods used in the installation of interdivisional cable for the PMS voting logic. The inspectors reviewed the separation between fiber optic cables to verify if distance and fire zone separation requirements, from the different divisions, were met to maintain the integrity of the PMS voting logic for these Class 1E communication cables.

The inspectors reviewed the PCD associated with this ITAAC to verify the analysis documented the effects of fire damage or damage to any single raceway carrying PMS interconnection cables potentially defeating the PMS voting logic.

b. Findings

No findings were identified.

IMC 2504, Construction Inspection Program – Inspection of Construction and Operational Programs

1P01 Construction QA Criterion 16

- 35007-A16 Appendix 16. Inspection of Criterion XVI Corrective Action
- 35007-A16.04 Inspection Requirements and Guidance
- 35007-A16.04.02 Inspection of QA Program Implementation

a. Inspection Scope

The inspection team conducted multiple activities in order assess the Vogtle Units 3 and 4 safety conscious work environment (SCWE), as part of the annual CAP inspection. The team interviewed seventy-three individuals from across Units 3 and 4, including licensee and contractor staff for Cyber Security; ITAAC; Initial Test Program (ITP); Maintenance; Field Engineering; and Richmond County Constructors electrician groups and interviewed senior level managers across the organization. The NRC inspectors reviewed Policy 701, "Vogtle 3 and 4 Employee Concerns Program," and Employee Concern Program (ECP) Work Instructions. The team interviewed ECP personnel to understand how the ECP is being implemented for the construction and SNC organizations at Vogtle 3 and 4. The team also interviewed US Alliance contractor personnel responsible for the 2022 SCWE survey.

Additionally, the team reviewed a sample of ECP files, work environment assessments (WEAs) from 2021 and 2022, condition reports (CRs) and technical evaluations (TEs) associated with SCWE concerns, and the Vogtle 2022 SCWE survey to determine if the licensee provided adequate resolution in accordance with the ECP policy, SCWE policy, and CAP procedure ND-AD-002, "Nuclear Development Corrective Action Program." The team reviewed meeting minutes from the Nuclear Safety Culture Monitoring Panel meetings from the first quarter of 2022 to determine if the minutes captured the items discussed during the panel meetings and inputs were used from the monitoring panels to assess safety culture at the site.

Assessment

The NRC's Final Safety Culture Policy Statement [U.S. Nuclear Regulatory Commission, "Final Safety Culture Policy Statement," Federal Register, Vol. 76, No. 114, June 14, 2011, pp. 34773-34778] applies to all NRC licensees, applicants, and vendors. It defines Nuclear Safety Culture as, "the core values and behaviors resulting from a collective commitment by leaders and individuals to emphasize safety over competing goals to ensure protection of people and the environment." The policy statement discusses nine traits of a positive safety culture. These include, but are not limited to, leadership safety values and actions, work processes, problem identification and resolution, and an environment for raising concerns. As stated in the Final Safety Culture Policy Statement, "[a] trait, in this case, is a pattern of thinking, feeling, and behaving that emphasizes safety, particularly in goal conflict situations, e.g., production, schedule, and the cost of the effort versus safety." Under each of the traits are subcategories referred to as the attributes of a healthy safety culture [NUREG-2165, "Safety Culture Language," dated March 2014 ADAMS Accession No. ML14083A200].

The inspectors determined that the majority of the staff is willing to raise safety and quality concerns through multiple avenues without fear of retaliation and feel that they are empowered to stop work when they identify issues. In addition, the licensee staff stated that the incorporation of the SNC senior managers into the construction organizations to help with engagement and ownership of the construction project is viewed favorably by the staff. The NRC determined that many of the previous issues related to chilled work environment have been addressed and corrected.

The inspectors also determined that while the majority of the licensee staff indicated that they would be willing to raise safety concerns without fear of retaliation, some staff in more than one group indicated that they do not feel free to raise concerns without fear of retaliation because there is a perception that either: 1) concerns raised will not be addressed or 2) that they might be retaliated against. The NRC inspectors found that multiple groups do not have confidence in the CAP or that anything is being done about their concerns. Specifically, some expressed concern that when issues are brought up, documented, discussed, and then closed, they often get closed without real action to address the concerns. Some individuals indicated that they rarely or never receive feedback on their concerns and must seek it out. Some indicated that they never received training on how to use SNC CR process/program or how to receive feedback from the CR system. Similarly, some individuals indicated that when they bring up concerns, individuals are frequently moved to other positions after expressing concerns. Additionally, multiple groups indicated that they do not have confidence in the site's employee concerns program. There is a perception among several groups about issues with overall effectiveness of the ECP as well as confidentiality with using the program.

The inspectors noted that the licensee did have a policy for the ECP program, however, the inspectors determined that Vogtle 3 and 4 does not have a detailed procedure that delineates the requirements of the ECP to support the policy. Vogtle does have a work instruction for ECP but the instruction is not sufficiently detailed to provide specific direction to the employee concerns professionals. The specific directions not delineated include what types of concerns warranted each type of ECP actions; when a CAP should be generated from an ECP investigation; or timeliness of case closure. In addition, individuals indicated that it seems that CRs and TEs are frequently being closed to ECP files. The NRC is concerned about this because when issues (CRs/TEs) are closed to ECP files, there are no additional CAP documents tracking completion of the actions or establishing due dates to ensure that the actions are being completed timely and in accordance with CAP standards. One example the team identified is that CRs and TEs associated with the SCWE survey recommendations were all closed in the CAP and the only tool tracking outstanding actions is the ECP database. This tracking system does not contain due dates or expected completion dates. Hence, the need for and tracking of important actions may not be visible to all appropriate stakeholders and it does not appear that actions are being tracked.

The Licensee entered the results of this assessment into the CAP as CR 50148707.

b. Findings

No findings were identified.

1P02 Construction QA Criterion 16

- 35007-A16.04 Inspection Requirements and Guidance
- 35007-A16.04.01 Inspection of QA Implementing Documents
- 35007-A16.04.02 Inspection of QA Program Implementation

a. Inspection Scope

The inspectors reviewed issues entered into the licensee's CAP daily to assess issues that might warrant additional follow-up inspection, to assess repetitive or long-term issues, to assess adverse performance trends, and to verify the CAP appropriately included regulatory required nonsafety-related structure system and components (SSCs). The inspectors periodically attended the licensee's CAP review meetings, held discussions with licensee and contractor personnel, and performed reviews of CAP activities during the conduct of other baseline inspection procedures. The inspectors reviewed conditions entered into the licensee's CAP to determine whether the issues were classified in accordance with the licensee's quality assurance program and CAP implementing procedures. The inspectors reviewed corrective actions associated with conditions entered into the CAP to determine whether appropriate actions to correct the issues were identified and implemented effectively, including immediate or short-term corrective actions, in accordance with the applicable quality assurance program requirements and Title 10 of the Code of Federal Regulations (10 CFR) Part 50, Appendix B. Criterion XVI. Additionally, the inspectors reviewed the corrective actions taken to determine whether they were commensurate with the significance of the associated conditions in accordance with the licensee's CAP implementing procedures. The inspectors completed reviews of CAP entry logs to verify issues from all aspects of the project, including equipment, human performance, and program issues, were being identified by the licensee and its contractors at an appropriate threshold and entered into the CAP as required by licensee's CAP implementing procedures.

b. Findings

No findings were identified.

4. OTHER INSPECTION RESULTS

4OA5 Other Activities

.1 <u>IP 92702: Follow-Up on Traditional Enforcement Actions Including Violations,</u> <u>Deviations, Confirmatory Action Letters, and Orders</u>

a. Inspection Scope

The inspectors reviewed commitments associated with two items from Confirmatory Orders (CO) Enforcement Action (EA)-18-130 and EA-18-171 (ADAMS Accession No. ML19249B612), issued to SNC Fleet Wide to include Farley, Hatch, Vogtle Units 1 and 2 (SNC-FW) and SNC Vogtle Units 3 and 4 (SNC-V) on November 20, 2019. The inspectors used the following IP sections to perform this inspection:

- 02.01 Documentation Review
- 02.02.a Corrective Actions

Training

Commitment 3.a): This commitment and action required within four (4) months of issuance of this confirmatory order, and until three (3) years thereafter, that SNC-FW and SNC-V will require all SNC employees who are onboarding to complete SCWE training, including training on 10 CFR 50.7, 10 CFR 52.5, 10 CFR 50.5, and 10 CFR 52.4, definition of adverse action as it appears in the RIS 2005-18, and acknowledge the SCWE policy within two (2) months of reporting to work. The inspectors reviewed the corrective actions described in TE 1058167 that onboarding employees from the time period of January 2021 to July 2022 completed the SCWE training as described and that the SNC SCWE policy was acknowledged within the specified time. The inspectors also reviewed corrective actions associated with NCV 5200025/2020012-01 and 05200026/2020012-01, Failure to Adequately Implement Requirements of CO EA-18-130 and 18-171, Commitment 3.a to determine if the corresponding actions were implemented in accordance with CAP procedure ND-AD-002.

The NRC acknowledges the potential organizational strain that may exist during the transition to operations and the importance of a SCWE. As a result, the NRC will continue to review the corrective actions associated with the three-year requirement for SNC-V. This action continues to be tracked by the licensee under TE 1058167.

Commitment 3.c): This commitment and action required that beginning no later than two (2) months of issuance of this confirmatory order, and until three (3) years thereafter, that SNC-FW and SNC-V will require all new SNC supervisors to receive SCWE training within six (6) months of their beginning work as a supervisor at SNC. For SNC-FW and SNC-V, the inspectors reviewed the corrective actions for TEs 1064351 and 1058169 that all new SNC supervisors (~120) received the training as described in the CO.

The NRC acknowledges the potential organizational strain that may exist during the transition to operations and the importance of a SCWE. As a result, the NRC will

continue to review the corrective actions associated with the three-year requirement for SNC-V. This action is being tracked by the licensee under TE 1058169.

Other Activities

Commitment 4.d): This commitment and action required within six (6) months of issuance of this order that SNC-V will obtain a third-party, independent SCWE survey of Vogtle Units 3 and 4 project sites. SNC-V will obtain a second third-party, independent SCWE survey of SNC-V no later than thirty (30) months after issuance of this confirmatory order. The results of each survey will be summarized into reports which will be made available for inspection by NRC. Recommendations (if any) from the survey reports will be entered into the CAP or ECP, as appropriate, depending on the nature of the recommendation, for disposition. The NRC reviewed the first independent SCWE survey as documented in inspection reports 05200025/2020012 and 05200026/2020012. The inspectors verified by a review of the corrective actions for TE 1062345 that the second independent SCWE survey for SNC-V was completed by a third-party vendor in May 2022.

The inspectors reviewed the corrective actions and enhancements associated with the second independent SCWE survey to verify that corrective actions were developed and appropriate to address the challenges/weaknesses identified in the assessment. SNC-V continues to track the corrective actions through the following CRs: 50139671, 50139675, and 50139678. The inspectors determined that Vogtle is implementing the requirements of 4.d in accordance with the order. As a part of the annual CAP, the NRC may follow-up with the corrective actions associated with this commitment.

b. Findings

No findings were identified.

4OA6 Meetings, Including Exit

.1 Exit Meeting.

On October 18, 2022, the NRC inspectors discussed the results of this inspection with Mr. G. Chick, VEGP Units 3 and 4 Executive Vice President, and other members of your staff. Proprietary information was reviewed during the inspection period but was not included in the inspection report.

SUPPLEMENTAL INFORMATION

KEY POINTS OF CONTACT

Licensees and Contractor Personnel

- R. Beilke, SNC ITAAC Project Manager
- M. Brummitt, SNC PI/CAP Project Director
- C. Castell, WEC Licensing Engineer
- K. Drudy, SNC ITAAC Project Manager
- L. Grissom, SNC Licensing Engineer
- M. Kelley, IEEE 384 ITAAC Project Manager
- D. Kettering; SNC Engineering
- S. Leighty, SNC Licensing Manager
- J. March, SNC Compliance & Concerns Director
- K. Phelps, SNC Compliance & Concerns Manager
- L. Pritchett, SNC Licensing Engineer
- K. Roberts, SNC ITAAC Manager
- G. Scott, SNC Licensing Engineer
- A. Tyson, SNC Project Manager-Technical Support

LIST OF ITEMS OPENED, CLOSED, AND DISCUSSED

Item Number	<u>Type</u>	<u>Status</u>	<u>Description</u>			
CO EA-18-130 and EA-18-171:						
Commitment 3a.	СО	Inspected	Provide SCWE training to all onboarding non-supervisory employees within two (2) months of reporting to work (Section 4OA5)			
Commitment 3c.	СО	Inspected	Provide SCWE training to all new SNC supervisors within six (6) months of their beginning work as a supervisor at SNC (Section 4OA5)			
Commitment 4d.	СО	Inspected	Obtain a second third-party, independent SCWE survey of Vogtle Units 3 and 4 project sites no later than thirty (30) months after issuance of the confirmatory order (Section 4OA5)			

LIST OF DOCUMENTS REVIEWED

Section 1A01

ITAAC Documents

SV3-1100-ITR-CTMTIR, ITAAC Technical Report Unit 3 Cables and Raceway Report for the Containment Building, Revision 0

SV3-1100-ITR-CTMT, ITAAC Technical Report Unit 3 Cable Separation Report for the Containment Building, Revision 0

Room 11501, Steam Generator 1 Operating Deck

Work Packages

SV3-1151-SHW-1002279, - U3 -CT -FABRICATE SCHEDULED CONDUIT SUPPORTS - EL 135' -3" -ROOM 11501 -AREA 1, Revision 0

SV3-1151-SHW-1003610, - U3 -CT -INSTALL SCHEDULED CONDUIT SUPPORTS -EL 135' -3" -ROOM 11501 -AREA 1. Revision 0

SV3-SMS-EJW-1055233, - U3 -CT- Install SMS Junction Box (SV3-SMS-EJ-YE013), EL. 135'-3", Area 1, Room 11501, Revision 0

Drawings

APP-1150-ER-103, Conduit Layout Containment Building West Compartment El. 135'-3" – 153'-0", Revision 0

APP-1150-ER-806, Conduit Layout Sections Containment Building West Compartment El. 135'-3" – 153'-0", Revision 0

Condition Reports

CR 50113713 – Design Routed Conduit Non-Conformances – Containment EL. 135'-0" (Rooms 11500, 11501, 11502, 11503)

CR 50134408 – ITAAC Review of Unit 3, Room 11501

CR 50146208 - NRC identified electrical support nonconformance

Technical Evaluations

TE 60039807 - ITAAC Review of Unit 3, Room 11501

TE 60043518 - NRC identified electrical support nonconformance

<u>Miscellaneous</u>

Work-To-Go-Status-Report – Room 11501 & Room 11503, Dated 7/6/2022

Room 11503, Upper Pressurizer Compartment

Work Packages

SV3-1152-ERW-1016529, U3 Install and Label Designed Class 1E Conduits- Containment, Elev. 135'Y- Room 11503-Area 2 (1 of 4), Revision 0

SV3-1152-ERW-1016592, U3 Install and Label Designed Class 1E Conduits 1 1/2"-

Containment, Elev. 135' 3"-Room 11503-Area 2 (3 of 4), Revision 0

SV3-1152-SHVV-1005367, U3 -CT -FABRICATE SCHEDULED CONDUIT SUPPORTS - EL 153' -AREA 2 -WP -5, Revision 0

Quality Control Inspection Records

SV3-1152-ERW-1016529 / Scope of Record: SV3-1152-ER-AZC26 – U3 Install and Label Designed Class 1E Conduits – Containment, Elev. 135'-3" – Room 11503-Area 2 (1 of 4)

Drawings

APP-1152-ER-103, Conduit Layout Containment Building Area 2 El. 176'-9" – Top Class 1E Conduits, Revision 7

Condition Reports

CR 50122549 - Bechtel QCE identified Nonconforming Conditions - Unit 3 Containment, Area 2, RM.11503

Technical Evaluations

TE 60039807 - ITAAC Review of Unit 3, Ro Bechtel QCE identified Nonconforming Conditions - Unit 3 Containment, Area 2, Room 11503

Miscellaneous

Work-To-Go-Status-Report – Room 11501 & Room 11503, Dated 7/6/2022

Room 11603, ADS Valve Area Lower Tier

Drawings

APP-1152-ER-101, Conduit Layout Containment Building Area 2 El. 135'-3" – 166'-0" Class 1E Conduits, Revision 11

APP-1152-ER-102, Conduit Layout Containment Building Area 2 El. 166'-0" – 176'-9" Class 1E Conduits, Revision 11

Condition Reports

CR 50112945 – Conduits 1152-ER-BXC01, BXC02 & BXC03 not per design FE Identified CR 50114731 – Bechtel QCE identified Nonconforming Conditions - Unit 3, Containment, RM.11603, Area 2

CR 50114761 – Bechtel QCE identified Nonconforming Conditions - Unit 3, Containment, RM.11603, Area 2

CR 50146209 – NRC identified broken flex conduit in Unit 3 Room 11603

Section 1A02

ITAAC Documents

SV3-1200-ITR-AUXNRDIR, ITAAC Technical Report Unit 3 Cables and Raceway Report for the Non-Radiologically Controlled Area of the Auxiliary Building, Revision 0 SV3-1200-ITR-AUXNRD, ITAAC Technical Report Unit 3 Cable Separation Report for the Non-Radiologically Controlled Area of the Auxiliary Building, Revision 0

Drawings

APP-ECS-E9-040, Electrical Raceway and Cable Identification Markers, Revision 3

Condition Reports

CR 50146212, NRC Identified Roxtec Gland nonconformance in Unit 3 Room 12305 CR 50144418, NRC-Identified cables not properly secured in Roxtec glands in Unit 3 Room

CR 50148476, NRC Identified - Editorial error in SV3-1200-ITR-AUXNRDIR

CR 50148760, NRC Identified: Inspection Review of ITAAC PCD SV3-1200-ITR-AUXNRD

<u>Miscellaneous</u>

APP-JE53-JOM-001, AP1000 Class 1E Resistance Temperature Detector N9002 Technical Manual, Revision 3

Section 1A03

ITAAC Documents

SV3-1100-ITR-CTMTIR, ITAAC Technical Report Unit 3 Cables and Raceway Report for the Containment Building, Revision 0

SV3-1100-ITR-CTMT, ITAAC Technical Report Unit 3 Cable Separation Report for the Containment Building, Revision 0

Room 11501, Steam Generator 1 Operating Deck

Work Packages

SV3-1151-SHW-1002279, - U3 -CT -FABRICATE SCHEDULED CONDUIT SUPPORTS - EL 135' -3" -ROOM 11501 -AREA 1, Revision 0

SV3-1151-SHW-1003610, - U3 -CT -INSTALL SCHEDULED CONDUIT SUPPORTS -EL 135' -3" -ROOM 11501 -AREA 1, Revision 0

SV3-SMS-EJW-1055233, - U3 -CT- Install SMS Junction Box (SV3-SMS-EJ-YE013), EL. 135'-3", Area 1, Room 11501, Revision 0

Drawings

APP-1150-ER-103, Conduit Layout Containment Building West Compartment El. 135'-3" – 153'-0", Revision 0

APP-1150-ER-806, Conduit Layout Sections Containment Building West Compartment El. 135'-3" – 153'-0", Revision 0

Condition Reports

CR 50113713 – Design Routed Conduit Non-Conformances – Containment EL. 135'-0" (Rooms 11500, 11501, 11502, 11503)

CR 50134408 - ITAAC Review of Unit 3, Room 11501

CR 50146208 - NRC identified electrical support nonconformance

Technical Evaluations

TE 60039807 - ITAAC Review of Unit 3, Room 11501

TE 60043518 - NRC identified electrical support nonconformance

Miscellaneous

Work-To-Go-Status-Report – Room 11501 & Room 11503, Dated 7/6/2022

Room 11503, Upper Pressurizer Compartment

Work Packages

SV3-1152-ERW-1016529, U3 Install and Label Designed Class 1E Conduits- Containment, Elev. 135'Y- Room 11503-Area 2 (1 of 4), Revision 0

SV3-1152-ERW-1016592, U3 Install and Label Designed Class 1E Conduits 1 1/2"-

Containment, Elev. 135' 3"-Room 11503-Area 2 (3 of 4), Revision 0

SV3-1152-SHVV-1005367, U3 -CT -FABRICATE SCHÉDULED CONDUIT SUPPORTS - EL 153' -AREA 2 -WP -5, Revision 0

Quality Control Inspection Records

SV3-1152-ERW-1016529 / Scope of Record: SV3-1152-ER-AZC26 – U3 Install and Label Designed Class 1E Conduits – Containment, Elev. 135'-3" – Room 11503-Area 2 (1 of 4)

Drawings

APP-1152-ER-103, Conduit Layout Containment Building Area 2 El. 176'-9" – Top Class 1E Conduits, Revision 7

Condition Reports

CR 50122549 - Bechtel QCE identified Nonconforming Conditions - Unit 3 Containment, Area 2, RM.11503

Technical Evaluations

TE 60039807 - ITAAC Review of Unit 3, Ro Bechtel QCE identified Nonconforming Conditions - Unit 3 Containment, Area 2, Room 11503

Miscellaneous

Work-To-Go-Status-Report – Room 11501 & Room 11503, Dated 7/6/2022

Room 11603, ADS Valve Area Lower Tier

Drawings

APP-1152-ER-101, Conduit Layout Containment Building Area 2 El. 135'-3" – 166'-0" Class 1E Conduits, Revision 11

APP-1152-ER-102, Conduit Layout Containment Building Area 2 El. 166'-0" – 176'-9" Class 1E Conduits, Revision 11

Condition Reports

CR 50112945 – Conduits 1152-ER-BXC01, BXC02 & BXC03 not per design FE Identified CR 50114731 – Bechtel QCE identified Nonconforming Conditions - Unit 3, Containment, RM.11603, Area 2

CR 50114761 – Bechtel QCE identified Nonconforming Conditions - Unit 3, Containment, RM.11603, Area 2

CR 50146209 – NRC identified broken flex conduit in Unit 3 Room 11603

Section 1A04

ITAAC Documents

SV3-1200-ITR-AUXNRDIR, ITAAC Technical Report Unit 3 Cables and Raceway Report for the Non-Radiologically Controlled Area of the Auxiliary Building, Revision 0

SV3-1200-ITR-AUXNRD, ITAAC Technical Report Unit 3 Cable Separation Report for the Non-Radiologically Controlled Area of the Auxiliary Building, Revision 0

Drawings

APP-ECS-E9-040, Electrical Raceway and Cable Identification Markers, Revision 3

Condition Reports

CR 50146212, NRC Identified Roxtec Gland nonconformance in Unit 3 Room 12305 CR 50144418, NRC-Identified cables not properly secured in Roxtec glands in Unit 3 Room 12304

CR 50148476, NRC Identified - Editorial error in SV3-1200-ITR-AUXNRDIR

CR 50148760, NRC Identified: Inspection Review of ITAAC PCD SV3-1200-ITR-AUXNRD

Miscellaneous

APP-JE53-JOM-001, AP1000 Class 1E Resistance Temperature Detector N9002 Technical Manual, Revision 3

Section 1A05

ITAAC Documents

SV3-1200-ITR-AUXNRDIR, ITAAC Technical Report Unit 3 Cables and Raceway Report for the Non-Radiologically Controlled Area of the Auxiliary Building, Revision 0

SV3-1200-ITR-AUXNRD, ITAAC Technical Report Unit 3 Cable Separation Report for the Non-Radiologically Controlled Area of the Auxiliary Building, Revision 0

Drawings

APP-ECS-E9-040, Electrical Raceway and Cable Identification Markers, Revision 3

Condition Reports

CR 50146212, NRC Identified Roxtec Gland nonconformance in Unit 3 Room 12305 CR 50144418, NRC-Identified cables not properly secured in Roxtec glands in Unit 3 Room 12304

CR 50148476, NRC Identified - Editorial error in SV3-1200-ITR-AUXNRDIR CR 50148760, NRC Identified: Inspection Review of ITAAC PCD SV3-1200-ITR-AUXNRD

Miscellaneous

APP-JE53-JOM-001, AP1000 Class 1E Resistance Temperature Detector N9002 Technical Manual, Revision 3

Section 1A06

ITAAC Documents

SV3-1100-ITR-CTMTIR, ITAAC Technical Report Unit 3 Cables and Raceway Report for the Containment Building, Revision 0

SV3-1100-ITR-CTMT, ITAAC Technical Report Unit 3 Cable Separation Report for the Containment Building, Revision 0

Room 11501, Steam Generator 1 Operating Deck

Work Packages

SV3-1151-SHW-1002279, - U3 -CT -FABRICATE SCHEDULED CONDUIT SUPPORTS - EL 135' -3" -ROOM 11501 -AREA 1, Revision 0

SV3-1151-SHW-1003610, - U3 -CT -INSTALL SCHEDULED CONDUIT SUPPORTS -EL 135' -3" -ROOM 11501 -AREA 1, Revision 0

SV3-SMS-EJW-1055233, - U3 -CT- Install SMS Junction Box (SV3-SMS-EJ-YE013), EL. 135'-3", Area 1, Room 11501, Revision 0

Drawings

APP-1150-ER-103, Conduit Layout Containment Building West Compartment El. 135'-3" – 153'-0", Revision 0

APP-1150-ER-806, Conduit Layout Sections Containment Building West Compartment El. 135'-3" – 153'-0", Revision 0

Condition Reports

CR 50113713 – Design Routed Conduit Non-Conformances – Containment EL. 135'-0" (Rooms 11500, 11501, 11502, 11503)

CR 50134408 - ITAAC Review of Unit 3, Room 11501

CR 50146208 - NRC identified electrical support nonconformance

Technical Evaluations

TE 60039807 - ITAAC Review of Unit 3, Room 11501

Miscellaneous

Work-To-Go-Status-Report – Room 11501 & Room 11503, Dated 7/6/2022

Room 11503, Upper Pressurizer Compartment

Work Packages

SV3-1152-ERW-1016529, U3 Install and Label Designed Class 1E Conduits- Containment, Elev. 135'Y- Room 11503-Area 2 (1 of 4), Revision 0

SV3-1152-ERW-1016592, U3 Install and Label Designed Class 1E Conduits 1 1/2"-

Containment, Elev. 135' 3"-Room 11503-Area 2 (3 of 4), Revision 0

SV3-1152-SHVV-1005367, U3 -CT -FABRICATE SCHEDULED CONDUIT SUPPORTS - EL 153' -AREA 2 -WP -5, Revision 0

Quality Control Inspection Records

SV3-1152-ERW-1016529 / Scope of Record: SV3-1152-ER-AZC26 – U3 Install and Label Designed Class 1E Conduits – Containment, Elev. 135'-3" – Room 11503-Area 2 (1 of 4)

Drawings

APP-1152-ER-103, Conduit Layout Containment Building Area 2 El. 176'-9" – Top Class 1E Conduits, Revision 7

Condition Reports

CR 50122549 - Bechtel QCE identified Nonconforming Conditions - Unit 3 Containment, Area 2, RM.11503

Technical Evaluations

TE 60039807 - ITAAC Review of Unit 3, Ro Bechtel QCE identified Nonconforming Conditions - Unit 3 Containment, Area 2, Room 11503

Miscellaneous

Work-To-Go-Status-Report – Room 11501 & Room 11503, Dated 7/6/2022

Room 11603, ADS Valve Area Lower Tier

Drawings

APP-1152-ER-101, Conduit Layout Containment Building Area 2 El. 135'-3" – 166'-0" Class 1E Conduits, Revision 11

APP-1152-ER-102, Conduit Layout Containment Building Area 2 El. 166'-0" – 176'-9" Class 1E Conduits, Revision 11

Condition Reports

CR 50112945 – Conduits 1152-ER-BXC01, BXC02 & BXC03 not per design FE Identified CR 50114731 – Bechtel QCE identified Nonconforming Conditions - Unit 3, Containment, RM.11603, Area 2

CR 50114761 – Bechtel QCE identified Nonconforming Conditions - Unit 3, Containment, RM.11603, Area 2

CR 50146209 – NRC identified broken flex conduit in Unit 3 Room 11603

Section 1A07

ITAAC Documents

SV3-1200-ITR-AUXNRDIR, ITAAC Technical Report Unit 3 Cables and Raceway Report for the Non-Radiologically Controlled Area of the Auxiliary Building, Revision 0

SV3-1200-ITR-AUXNRD, ITAAC Technical Report Unit 3 Cable Separation Report for the Non-Radiologically Controlled Area of the Auxiliary Building, Revision 0

Drawings

APP-ECS-E9-040, Electrical Raceway and Cable Identification Markers, Revision 3

Condition Reports

CR 50146212, NRC Identified Roxtec Gland nonconformance in Unit 3 Room 12305 CR 50144418, NRC-Identified cables not properly secured in Roxtec glands in Unit 3 Room 12304

CR 50148476, NRC Identified - Editorial error in SV3-1200-ITR-AUXNRDIR CR 50148760, NRC Identified: Inspection Review of ITAAC PCD SV3-1200-ITR-AUXNRD

Miscellaneous

APP-JE53-JOM-001, AP1000 Class 1E Resistance Temperature Detector N9002 Technical Manual, Revision 3

Section 1A08

ITAAC Documents

SV3-1100-ITR-CTMTIR, ITAAC Technical Report Unit 3 Cables and Raceway Report for the Containment Building, Revision 0

SV3-1100-ITR-CTMT, ITAAC Technical Report Unit 3 Cable Separation Report for the Containment Building, Revision 0

Room 11501, Steam Generator 1 Operating Deck

Work Packages

SV3-1151-SHW-1002279, - U3 -CT -FABRICATE SCHEDULED CONDUIT SUPPORTS - EL 135' -3" -ROOM 11501 -AREA 1, Revision 0

SV3-1151-SHW-1003610, - U3 -CT -INSTALL SCHEDULED CONDUIT SUPPORTS -EL 135' -3" -ROOM 11501 -AREA 1, Revision 0

SV3-SMS-EJW-1055233, - U3 -CT- Install SMS Junction Box (SV3-SMS-EJ-YE013), EL. 135'-3", Area 1, Room 11501, Revision 0

Drawings

APP-1150-ER-103, Conduit Layout Containment Building West Compartment El. 135'-3" – 153'-0", Revision 0

APP-1150-ER-806, Conduit Layout Sections Containment Building West Compartment El. 135'-3" – 153'-0", Revision 0

Condition Reports

CR 50113713 – Design Routed Conduit Non-Conformances – Containment EL. 135'-0" (Rooms 11500, 11501, 11502, 11503)

CR 50134408 – ITAAC Review of Unit 3, Room 11501

CR 50146208 - NRC identified electrical support nonconformance

Technical Evaluations

TE 60039807 - ITAAC Review of Unit 3, Room 11501

Miscellaneous

Work-To-Go-Status-Report – Room 11501 & Room 11503, Dated 7/6/2022

Room 11503, Upper Pressurizer Compartment

Work Packages

SV3-1152-ERW-1016529, U3 Install and Label Designed Class 1E Conduits- Containment, Elev. 135'Y- Room 11503-Area 2 (1 of 4), Revision 0

SV3-1152-ERW-1016592, U3 Install and Label Designed Class 1E Conduits 1 1/2"-

Containment, Elev. 135' 3"-Room 11503-Area 2 (3 of 4), Revision 0

SV3-1152-SHVV-1005367, U3 -CT -FABRICATE SCHEDULED CONDUIT SUPPORTS - EL 153' -AREA 2 -WP -5, Revision 0

Quality Control Inspection Records

SV3-1152-ERW-1016529 / Scope of Record: SV3-1152-ER-AZC26 – U3 Install and Label Designed Class 1E Conduits – Containment, Elev. 135'-3" – Room 11503-Area 2 (1 of 4)

Drawings

APP-1152-ER-103, Conduit Layout Containment Building Area 2 El. 176'-9" – Top Class 1E Conduits, Revision 7

Condition Reports

CR 50122549 - Bechtel QCE identified Nonconforming Conditions - Unit 3 Containment, Area 2, RM.11503

Technical Evaluations

TE 60039807 - ITAAC Review of Unit 3, Ro Bechtel QCE identified Nonconforming Conditions - Unit 3 Containment, Area 2, Room 11503

Miscellaneous

Work-To-Go-Status-Report – Room 11501 & Room 11503, Dated 7/6/2022

Room 11603, ADS Valve Area Lower Tier

Drawings

APP-1152-ER-101, Conduit Layout Containment Building Area 2 El. 135'-3" – 166'-0" Class 1E Conduits, Revision 11

APP-1152-ER-102, Conduit Layout Containment Building Area 2 El. 166'-0" – 176'-9" Class 1E Conduits, Revision 11

Condition Reports

CR 50112945 – Conduits 1152-ER-BXC01, BXC02 & BXC03 not per design FE Identified CR 50114731 – Bechtel QCE identified Nonconforming Conditions - Unit 3, Containment, RM.11603, Area 2

CR 50114761 – Bechtel QCE identified Nonconforming Conditions - Unit 3, Containment, RM.11603, Area 2

CR 50146209 - NRC identified broken flex conduit in Unit 3 Room 11603

Section 1A09

ITAAC Documents

SV3-1200-ITR-AUXNRDIR, ITAAC Technical Report Unit 3 Cables and Raceway Report for the Non-Radiologically Controlled Area of the Auxiliary Building, Revision 0

SV3-1200-ITR-AUXNRD, ITAAC Technical Report Unit 3 Cable Separation Report for the Non-Radiologically Controlled Area of the Auxiliary Building, Revision 0

Drawings

APP-ECS-E9-040, Electrical Raceway and Cable Identification Markers, Revision 3

Condition Reports

CR 50146212, NRC Identified Roxtec Gland nonconformance in Unit 3 Room 12305

CR 50144418, NRC-Identified cables not properly secured in Roxtec glands in Unit 3 Room 12304

CR 50148476, NRC Identified - Editorial error in SV3-1200-ITR-AUXNRDIR

CR 50148760, NRC Identified: Inspection Review of ITAAC PCD SV3-1200-ITR-AUXNRD

Miscellaneous

APP-JE53-JOM-001, AP1000 Class 1E Resistance Temperature Detector N9002 Technical Manual, Revision 3

Section 1A10

ITAAC Technical Report SV3-CSR-ITR-800807; Unit 3 Cable Separation Report for Analysis: ITAAC 3.3.00.07d.iv.b (NRC Index #807), Revision 2

E&DCR No. APP-G1-GEF-850217; Leaky coax Cable IEEE 384 Separation Reduction (ESR 50144956), Revision 0

ND-22-0473; SNC letter for Resubmittal of ITAAC Closure Notification on Completion of ITAAC 3.3.00.07d.iv.b [Index Number 807], Dated July 15, 2022

Section 1A11

2.2.01.11a.i-U4-EQRR-PCD001, "Containment System (CNS) EQ Reconciliation Report (EQRR)," Revision 0

ND-18-1100, "Southern Nuclear Operating Company Resubmittal Notice of Uncompleted ITAAC 225 days Prior to Initial Fuel Load Item 2.2.01.11a.i (Index Number 114)," Revision 0 SV4-PV11-VBR-005, WEC Document No. APP-PV11-VBR-005, "Equipment Qualification Summary for Motor-Operated TRICENTRIC Butterfly Valve for Use in the AP1000 Plant," Revision 2

SV4-PV11-VBR-006, WEC Document No. APP-PV11-VBR-006, "Equipment Qualification Data Package for Motor-Operated TRICENTRIC Butterfly Valve for Use in the AP1000 Plant," Revision 3

SV4-PV11-Z0-001, WEC Document No. APP-PV11-Z0-001, "Design Specification for Butterfly Valves, ASME Boiler and Pressure Vessel Code Section III, Class 2 and 3," Revision 3 SV4-PV11-Z0D-123, WEC Document No. APP-PV11-Z0D-123, "PV11 Datasheet 123," Revision 7

SV4-PV11-Z0D-124, WEC Document No. APP-PV11-Z0D-124, "PV11 Datasheet 124," Revision 5

APP-PV11-GEF-080 - Engineering & Design Coordination Report (E&DCR), "PV11 Equipment Qualification Documentation Updates for ITAAC Inspection Comments," Revision

APP-PV00-GEF-008, "Use of Ground and Clamps with Valve Commodities Not Using ASCO Solenoids (50110181), Revision 0

APP-PV00-GEF-011, "Addressing Requirements for Loctite in MOV Qualification Documentation," Revision 0

APP-GW-GEF-1923, "Electromagnetic Compatibility Changes to PV01 and PV11 and Grease Changes to PV01," Revision 0.

APP-PV11-GEF-850000, "Update to APP-PV11-VBR-005," Revision 0

SV4-PV11-V2-123001, "Motor Operated Butterfly Valve 6" Class 150 SST," Revision 1

SV4-PV11-V2-123002, "Motor Operated Butterfly Valve 6" Class 150 SST," Revision 1

SV4-PV11-V2-124001, "Motor Operated Butterfly Valve 10" Class 150 CS," Revision 2

SV4-PV11-V2-124002, "Motor Operated Butterfly Valve 10" Class 150 CS," Revision 2

Section 1A12

SV4-PXS-ITR-800182, "Unit 4: ITAAC 182 Walkdown 2.2.03.08c.iii NRC Index Number 182," Revision 0

ESR 50135607, "Action Needed to Submit U4 ITAAC 182 ICN Due to Incorrect Slope on SV4-PXS-PLW-035," Revision 0

SV4-PXS-M6K-800182, "RCS Cold Leg to the High Point of the CMT 'A' Inlet Line," Revision 1 SV4-PXS-M6K-801182, "RCS Cold Leg to the High Point of the CMT 'B' Inlet Line," Revision 1 SV4-PXS-M6K-802182, "RCS Hot Leg to the High Point of the PRHR HX Inlet Line," Revision 1

SV4-PXS-PLW-050, "Passive Core Cooling System Containment Building Room 11400/ 11302 Cold Leg to CMT 02A Inlet," Revision 4

SV4-PXS-PLW-05A, "Passive Core Cooling System Containment Building Room 11400 Cold Leg to CMT 02A INLET," Revision 2

SV4-RCS-PLW-061, "Reactor Coolant System Containment Bldg Room 11302/ 11400 RCS Line from Cold Leg to CMT 02B," Revision 4

SV4-PXS-PLW-060, "Passive Core Cooling System Containment Bldg Room 11400 PXS Line from Cold Leg to CMT 02B," Revision 3

SV4-RCS-PLW-03A, "Reactor Coolant System Containment Building Room 11301 ADS Stage 4 Piping West Compartment," Revision 2

SV4-RCS-PLW-03C, "Reactor Coolant System Containment Building Room 11401 PRHR Supply Line," Revision 2

SV4-RCS-PLW-032, "Reactor Coolant System Containment Building Rooms 11303/ 11401 PRHR Supply Line," Revision 3

SV4-RCS-PLW-033, "Reactor Coolant System Containment Building Room 11303 PRHR Supply Line," Revision 3

SV4-RCS-PLW-034, "Reactor Coolant System Containment Building Rooms 11303/ 11500 PRHR Supply Line," Revision 2

SV4-PXS-PLW-035, "Passive Core Cooling System Containment Building Room 11500 PRHR Supply Line," Revision 2

Section 1A13

SV4-PXS-FSK-900191, "ITAAC Verification Volume of the IRWST," Revision 0 SV4-1000-P2-935, "Nuclear Island General Arrangement Section W1-W1," Revision 1 SV4-1030-P2-001, "Nuclear Island General Arrangement Plan at EL 100'-0" & 107'-2"," Revision 4

SV4-MW01-FSK-891550, "Unit 4 ADS Sparger As-Built Elevation Verification," Revision 0 U43-CV-IRWST-SWR1137276, "Unit 4 IRWST ITAAC Volume," 10/29/2019 APP-PXS-M3C-081, "In-Containment Refueling Water Storage Tank (IRWST) Surface Area

and Volume Height," Revision 0

Section 1A14

ITAAC Documents

SV4-DAS-ITR-800519, ITAAC Technical Report Unit 4 Inspection Results of Diverse Actuation System (DAS) Design Process: Installation Phase: ITAAC 2.5.01.04 NRC Index Number: 519, Revision Number 0

Work Packages

SV4-DAS-JDW-1107744, U4 – AUX – Install DAS Cabinets (SV4-DAS-JD-001/002/003) – EL 135'3" – Rm 12554 – Area 4, Revision 0

Miscellaneous

26139-000-4MP-T81C-N3301, Electrical Equipment Installation, Revision 9

APP-GW-GLR-623, AP1000 Design Certification ITAAC 2.5.01.04: Diverse Actuation System Design Process Technical Report, Revision 0

B-GEN-ITPCI-002, Diverse Actuation System (DAS) Cabinets, Version 3.0

SV4-GW-GCW-0126, AP1000 Vogtle Unit 4 Diverse Actuation System (DAS) ASU PC Update and Application Ver 1.11 Installation, Revision 0

Section 1A15

ITAAC Documents

SV4-CSR-ITR-800812, ITAAC Technical Report Unit 4 Cable Separation Report for PMS As-Built Class 1E Routing and Separation, Revision 0

Drawings

APP-1221-ER-101, Auxiliary Building Area 1 Class 1E Conduit Arrangement Plan at Elevation 82'-6", Revision 17

APP-1222-ER-101, Auxiliary Building Area 2 Class 1E Conduit Arrangement Plan at Elevation 82'-6", Revision 17

APP-1231-ER-105, Auxiliary Building Area 1 Class 1E Conduit Arrangement at Elevation 100'-0" Room 12304 (Partial), Revision 8

APP-1231-ER-106, Auxiliary Building Area 1 Class 1E Conduit Arrangement Plan at Elevation 100'-0" Room 12304 & 12300 (Partial), Revision 9

APP-1231-ER-110, Auxiliary Building Area 1 Class 1E Conduit Arrangement at Elevation 100'-0" Sections and Details, Revision 4

APP-1232-ER-103, Auxiliary Building Area 2 Class 1E Conduit Arrangement Plan at Elevation 100'-0" Room 12303 & 12300 (Partial), Revision 6

APP-1232-ER-105, Auxiliary Building Area 2 Class 1E Conduit Arrangement at Elevation 100'-0" Room 12301, Revision 7

APP-1232-ER-117, Auxiliary Building Area 2 Class 1E Conduit Arrangement Plan at Elevation 100'-0" Room 12300 (Partial), Revision 2

Cable Pull Tickets

SV4-PMS-EW-JDBCCA0101BZA[PT] Revision 2, dated: 2021-06-03

SV4-PMS-EW-JDBCCA0101CZA[PT] Revision 2, dated: 2021-06-03

SV4-PMS-EW-JDBCCA0201BZA[PT] Revision 2, dated: 2021-06-03

SV4-PMS-EW-JDBCCA0201CZA[PT] Revision 2, dated: 2021-06-03

SV4-PMS-EW-JDBCCB0101BZB[PT] Revision 2, dated: 2021-06-03

SV4-PMS-EW-JDBCCB0101CZB[PT] Revision 2, dated: 2021-06-03

SV4-PMS-EW-JDBCCB0201BZB[PT] Revision 2, dated: 2021-06-03 SV4-PMS-EW-JDBCCB0201CZB[PT] Revision 2, dated: 2021-06-03

Section 1P01

Condition Reports

50107464

50108864

50110999

50131955

50100016

50101441

50078068

50107382

50148707

Corrective Action Reports

CAR 80007622

Technical Evaluations

TE 60031125

TE 60039036

TE 60031753

Work Environment Assessments

WEA 20210514-10

WEA 202102160005

WEA 202109270009

WEA 202111180008

WEA 202110070002

WEA 202108230001

WEA 20210607-4

WEA 20211102-17

WEA 202205020004

WEA 20220202-26

Employee Concerns Program Files

ECP IR 20210916-12

ECP IR 20210928-23

ECP IR 202110210001

ECP IR 20220412-18

ECP 202103230002

ECP 20210419-4

ECP 20210315-8

ECP 20200003049

ECP 20200003050

ECP 20200001332

EOD 0004000 40

ECP 20210923-12

ECP 20210607-4

ECP 20210902-4

ECP 202102170001

ECP 202107300001

ECP 20210719-25

ECP 202108060002

ECP 202109160001

ECP 202103230002 ECP 20210315-8

Miscellaneous

Vogtle 3&4 Employee Concerns Program, PROJECT ECP WORK INSTRUCTIONS, Revision 1

Nuclear Safety Culture Monitoring Panels (NSCMP), Meeting Minutes, Dated 1Q 2022 Cyber Security Action Plan Status

Utilities Service Alliance Sitewide SCWE Survey Executive Summary, Dated May 18, 2022 Utilities Service Alliance Vogtle 2022 Survey Nuclear Safety Culture Assessment 2022, Dated March 14-23, 2022

Section 1P02

APP-GW-GAP-420, "Engineering and Design Coordination Reports," Revision 21 APP-GW-GAP-428, "Nonconformance and Disposition Report," Revision 20 ND-AD-002, "Nuclear Development Program Corrective Action Program," Version 32.0 ND-AD-002-027, "Nonconforming Items," Version 10.0 ND-AD-002-028, "Corrective Action Program Instructions," Version 3.1

Section 40A5

Condition Reports

50070704

50071376

50128528

50139671

50139675

50139678

50140006

50144166

Corrective Action Reports

CAR 80004235

CAR 80004262

CAR 80007435

Technical Evaluations

TE 1058167

TE 1058169

TE 1062345

TE 60041454

Miscellaneous

Confirmatory Order EA-18-130 Item 3.a Validation Package, March 18, 2020

Confirmatory Order EA-18-130 Item 3.c Validation Package, July 21, 2020

ECP IR. No. 20220711-27

ECP IR. No. 20220711-28

ND-AD-014-F03, Nuclear Safety Culture - Performance Rating and SLT Report, Version 3.1 S-GE-305, SNC Employee SCWE Course: Maintaining a Good Safety Conscious Work Environment (SCWE) at Southern Nuclear

Utilities Service Alliance Sitewide SCWE Survey Executive Summary, Dated May 18, 2022

Utilities Service Alliance Vogtle 2022 Survey Nuclear Safety Culture Assessment 2022, Dated March 14-23, 2022 SCWE Training Record Spreadsheets.

LIST OF ACRONYMS

ADS	Automatic Depressurization System
CAP	Corrective Action Program
CCS	Component Cooling Water System
CFR	Code of Federal Regulations
CMT	Core Makeup Tank
CO	Confirmatory Orders
COL	Combined License
CR	Condition Report
DAS	Diverse Actuation System
ECP	Employee Concern Program
EQRR	Equipment Qualification Reconciliation Report
ESR	Engineering Services Request
E&DCR	Engineering & Design Coordination Report
IEEE	Institute of Electrical and Electronic Engineers
IMC	Inspection Manual Chapter
IP	Inspection Procedure
IR	Inspection Report
IRWST	In-Containment Refueling Water Storage Tank
ITAAC	Inspections, Tests, Analysis, and Inspection Criteria
ITP	Initial Test Program
MOV	Motor-Operated Valve
NCV	Noncited Violation
PCD	Principal Closure Document
NRC	Nuclear Regulatory Commission
PMS	Protection and Safety Monitoring System
RCS	Reactor Coolant System
SCWE	Safety Conscious Work Environment
SFS	Spent Fuel Pool Cooling System
SNC	Southern Nuclear Company
SSC	Structure, System, and Component
VEGP	Vogtle Electric Generating Plant
WEA	Work Environment Assessment
WEC	Westinghouse Electric Company

ITAAC INSPECTED

No.	ITAAC No.	Design Commitment	Inspections, Tests, Analysis	Acceptance Criteria
114	2.2.01.11a.i	11.a) The motor- operated and check valves identified in Table 2.2.1-1 perform an active safety-related function to change position as indicated in the table.	i) Tests or type tests of motor- operated valves will be performed to demonstrate the capability of each valve to operate under design conditions. ii) Inspections will be performed for the existence of a report verifying that the as-built motor- operated valves are bounded by the tests or type tests.	i) A test report exists and concludes that each motor-operated valve changes position as indicated in Table 2.2.1-1 under design conditions. ii) A report exists and concluded that the as-built motor-operated valves are bounded by the tests or type tests.
182	2.2.03.08c.iii	8.c) The PXS provides RCS makeup, boration, and safety injection during design basis events.	iii) Inspections of the routing of the following pipe lines will be conducted: — CMT inlet line, cold leg to high point — PRHR HX inlet line, hot leg to high point	iii) These lines have no downward sloping sections between the connection to the RCS and the high point of the line.
191	2.2.03.08c.vi.03	8.c) The PXS provides RCS makeup, boration, and safety injection during design basis events.	vi) Inspections of each of the following tanks will be conducted: 3.– IRWST	vi) The calculated volume of each of the following tanks is as follows: 3. IRWST > 73,100 ft3 between the tank outlet connection and the tank overflow

No.	ITAAC No.	Design Commitment	Inspections, Tests, Analysis	Acceptance Criteria
789	3.3.00.07aa	7.a) Class 1E electrical cables, communication cables associated with only one division, and raceways that route the Class 1E electrical cables and the communication cables are identified according to applicable color- coded Class 1E divisions.	Inspections of the as-built Class 1E cables and the as-built raceways that route the Class 1E cables will be conducted.	a) Class 1E electrical cables, and communication cables associated with only one division, and the raceways that route these cables inside containment are identified by the appropriate color code.
790	3.3.00.07ab	7.a) Class 1E electrical cables, communication cables associated with only one division, and raceways that route the Class 1E electrical cables and the communication cables are identified according to applicable color- coded Class 1E divisions.	Inspections of the as-built Class 1E cables and the as-built raceways that route the Class 1E cables will be conducted.	b) Class 1E electrical cables, and communication cables associated with only one division, and the raceways that route these cables in the non-radiologically controlled area of the auxiliary building are identified by the appropriate color code.

792	3.3.00.07ba	7.b) Class 1E divisional electrical cables and communication cables associated with only one division are routed in their respective divisional raceways.	Inspections of the as-built Class 1E divisional cables and the as-built raceways that route the Class 1E cables will be conducted.	a) Class 1E electrical cables and communication cables inside containment associated with only one division are routed in raceways assigned to the same division. There are no other safety division electrical cables in a raceway assigned to a different division.
793	3.3.00.07bb	7.b) Class 1E divisional electrical cables and communication cables associated with only one division are routed in their respective divisional raceways.	Inspections of the as-built Class 1E divisional cables and the as-built raceways that route the Class 1E cables will be conducted.	b) Class 1E electrical cables and communication cables in the non-radiologically controlled area of the auxiliary building associated with only one division are routed in raceways assigned to the same division. There are no other safety division electrical cables in a raceway assigned to a different division.

795	3.3.00.07c.i.a	7.c) Separation is maintained between Class 1E divisions in accordance with the fire areas as identified in Table 3.3-3.	i) Inspections of the asbuilt Class 1E division electrical cables, as-built communication cables associated with only one division, and the as-built raceways that route the Class 1E divisional electrical cables and communication cables located in the fire areas identified in Table 3.3-3 will be conducted.	i.a) Results of the inspection will confirm that the separation between Class 1E divisions in the non-radiologically controlled area of the auxiliary building is consistent with Table 3.3-3.
800	3.3.00.07d.ii.a	7.d) Physical separation is maintained between Class 1E divisions and non-Class 1E cables.	Inspections of the as-built raceways that route Class 1E cables will be performed to confirm that the separation between raceways that route Class 1E cables of different divisions, and between raceways that route Class 1E cables and raceways that route non-Class 1E cables is consistent with the following: ii.a) Within other plant areas (hazard areas), the minimum separation is defined by one of the following: 1) The minimum vertical separation is 5 feet and the minimum horizontal separation is 3 feet.	Results of the inspection will confirm that the separation between raceways that route Class 1E cables of different divisions, and between raceways that route Class 1E cables and raceways that route non-Class 1E cables is consistent with the following: ii.a) Within other plant areas inside containment (hazard areas), the separation meets one of the following: 1) The vertical separation is 5 feet or more and the horizontal separation is 3 feet or more.

2) The minimum vertical separation is 12 inches and the minimum horizontal separation is 6 inches for raceways containing only instrumentation and control and low-voltage power cables ≤2/0 AWG. This minimum vertical separation is 3 inches for the configuration with a conduit above and crossing the open tray at an angle equal to or greater than 45 degrees. 3) The minimum vertical separation is 12 inches and the minimum horizontal separation is 6 inches between a conduit and an open configuration for low- voltage power cables greater than 2/0 AWG but not greater than 750 kcmil. The vertical separation is 3 inches if a conduit is above and crossing an open tray at an angle equal to or greater than 45 degrees. 4) For configurations that involve exclusively limited energy content cables (instrumentation and control), the minimum vertical separation is 1 inch and the minimum horizontal separation is 1 inch. 5) For configurations involving an enclosed raceway and an open raceway with low-voltage power cables, the minimum vertical separation is 1 inch if the enclosed raceway is below the open raceway. 6) For configuration involving enclosed raceways, the minimum separation is 1 inch in both horizontal and vertical directions. 7) The minimum vertical separation is 1 inch and the minimum horizontal separation is 1 inch for

2) The minimum vertical separation is 12 inches and the minimum horizontal separation is 6 inches for raceways containing only instrumentation and control and low-voltage power cables ≤2/0 AWG. This minimum vertical separation may be reduced to 3 inches for the configuration with a conduit above and crossing the open tray at an angle equal to or greater than 45 degrees. 3) The minimum vertical separation is 12 inches and the minimum horizontal separation is 6 inches between a conduit and an open configuration for lowvoltage power cables greater than 2/0 AWG but not greater than 750 kcmil. The vertical separation may be reduced to 3 inches if a conduit is above and crossing an open tray at an angle equal to or greater than 45 degrees. 4) For configurations that involve exclusively limited energy content cables (instrumentation and control), the minimum vertical separation is 1 inch and the minimum horizontal separation is 1 inch. 5) For configurations that involve an enclosed raceway and an open raceway with lowvoltage power cables, the minimum vertical separation is 1 inch if the enclosed raceway is

separation is 1 inch for configurations with a non-safety conduit and a free air safety cable with low-voltage power cables and below.

below the open raceway. 6) For configurations that involve enclosed raceways, the minimum vertical and horizontal separation is 1 inch. 7)

801 3.3.00.07d.ii.b 7.d) Physical Inspections of the as-built Results of the inspection separation is raceways that route Class will confirm that the maintained 1E cables will be separation between between Class performed to confirm that raceways that route Class 1E divisions the separation between 1E cables of different and between raceways that route Class divisions, and between Class 1E 1E cables of different raceways that route Class divisions and divisions, and between 1E cables and raceways non-Class 1E raceways that route Class that route non-Class 1E cables. 1E cables and raceways cables is consistent with that route non-Class 1E the following: ii.b) Within cables is consistent with other plant areas inside the non-radiologically the following: ii.b) Within other plant areas (limited controlled area of the hazard areas), the auxiliary building (limited minimum separation is hazard areas), the defined by one of the separation meets one of following: 1) The minimum the following: 1) The vertical separation is 5 feet vertical separation is 5 feet and the minimum or more and the horizontal horizontal separation is 3 separation is 3 feet or feet. 2) The minimum more. 2) The minimum vertical separation is 12 vertical separation is 12 inches and the minimum inches and the minimum horizontal separation is 6 horizontal separation is 6 inches for raceways inches for raceways containing only containing only instrumentation and instrumentation and control and low-voltage control and low-voltage power cables ≤ 2/0 AWG. power cables ≤ 2/0 AWG. This minimum vertical This minimum vertical separation may be separation is 3 inches for reduced to 3 inches for the the configuration with a conduit above and configuration with a crossing the open tray at conduit above and an angle equal to or crossing the open tray at greater than 45 degrees. an angle equal to or greater than 45 degrees. 3) The minimum vertical separation is 12 inches 3) The minimum vertical and the minimum separation is 12 inches horizontal separation is 6 and the minimum inches between a conduit horizontal separation is 6 and an open configuration inches between a conduit for low- voltage power and an open configuration cables greater than 2/0 for low- voltage power AWG but not greater than cables greater than 2/0 AWG but not greater than 750 kcmil. The vertical separation is 3 inches if a 750 kcmil. The vertical conduit is above and separation may be reduced to 3 inches if a crossing an open tray at an angle equal to or conduit is above and greater than 45 degrees. crossing an open tray at 4) For configurations that an angle equal to or involve exclusively limited greater than 45 degrees. energy content cables 4) For configurations that (instrumentation and control), the minimum involve exclusively limited energy content cables vertical separation is 1 (instrumentation and inch and the minimum control), the minimum harizantal congration is vertical congration is 1

803	3.3.00.07d.iii.a	7.d) Physical separation is maintained between Class 1E divisions and between Class 1E divisions and non-Class 1E cables.	Inspections of the asbuilt raceways that route Class 1E cables will be performed to confirm that the separation between raceways that route Class 1E cables of different divisions, and between raceways that route Class 1E cables and raceways that route Class 1E cables and raceways that route non-Class 1E cables is consistent with the following: iii) Where minimum separation distances are not maintained, the circuits are run in enclosed raceways or barriers are provided.	Results of the inspection will confirm that the separation between raceways that route Class 1E cables of different divisions, and between raceways that route Class 1E cables and raceways that route non-Class 1E cables is consistent with the following: iii.a) Where minimum separation distances are not met inside containment, the circuits are run in enclosed raceways or barriers are provided.
804	3.3.00.07d.iii.b	7.d) Physical separation is maintained between Class 1E divisions and between Class 1E divisions and non-Class 1E cables.	Inspections of the asbuilt raceways that route Class 1E cables will be performed to confirm that the separation between raceways that route Class 1E cables of different divisions, and between raceways that route Class 1E cables and raceways that route Class 1E cables and raceways that route non-Class 1E cables is consistent with the following: iii) Where minimum separation distances are not maintained, the circuits are run in enclosed raceways or barriers are provided.	Results of the inspection will confirm that the separation between raceways that route Class 1E cables of different divisions, and between raceways that route Class 1E cables and raceways that route non-Class 1E cables is consistent with the following: iii.b) Where minimum separation distances are not met inside the non-radiologically controlled area of the auxiliary building, the circuits are run in enclosed raceways or barriers are provided.
807	3.3.00.07d.iv.b	7.d) Physical separation is maintained between Class 1E divisions and between Class 1E divisions and non-Class 1E cables.	Inspections of the asbuilt raceways that route Class 1E cables will be performed to confirm that the separation between raceways that route Gass 1E cables of different divisions, and between raceways that route	Results of the inspection will confirm that the separation between raceways that route Class 1E cables of different divisions, and between raceways that route Class 1E cables and raceways that route non-Class

812	3.3.00.07e	7.e) Class 1E communication cables which interconnect two divisions are routed and separated such that the Protection and Safety Monitoring System voting logic is not defeated by the loss of any single raceway or fire area.	Inspections of the asbuilt Class 1E communication cables will be conducted.	Class 1E communication cables which interconnect two divisions are routed and separated such that the Protection and Safety Monitoring System voting logic is not defeated by the loss of any single raceway or fire area.
-----	------------	---	---	--